



CARFAX® Vehicle History Report™

An independent company established in 1986

Vehicle Information:

2006 LEXUS GS 300

VIN: JTHCH96S660020165

SEDAN 4 DR

3.0L V6 F DOHC 24V

GASOLINE

ALL WHEEL DRIVE

[Standard Equipment](#) | [Safety Options](#)



No accidents reported to CARFAX



No other damage reported to CARFAX



CARFAX 1-Owner vehicle



At least 1 open recall



Personal vehicle



95 Last reported odometer reading



This CARFAX Vehicle History Report is based only on [information](#) supplied to CARFAX and available as of 6/28/18 at 5:41:54 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Ownership History

The number of owners is estimated

Owner 1

Year purchased

2006

Type of owner

Personal

Estimated length of ownership

11 yrs. 7 mo.

Owned in the following states/provinces

Michigan

Estimated miles driven per year

Last reported odometer reading

95



Title History

Owner 1

[Salvage](#) | [Junk](#) | [Rebuilt](#) | [Fire](#) | [Flood](#) | [Hail](#) | [Lemon](#)

No Problem

[Not Actual Mileage](#) | [Exceeds Mechanical Limits](#)

No Problem



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.

No Issues Reported

Structural Damage

No structural damage reported to CARFAX.

No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

Odometer Check

No indication of an odometer rollback.

No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.

 No Issues Reported**Manufacturer Recall**At least 1 manufacturer recall requires service. Locate an authorized [Lexus dealer](#) near you to schedule an appointment.**Recall Reported****Detailed History**

Glossary

Owner 1

Purchased: 2006
 Type: Personal
 Where: Michigan
 Est. length owned: 11/3/06 - present
 (11 yrs. 7 mo.)

Date:	Mileage:	Source:	Comments:
07/02/2006		NICB	Vehicle manufactured and shipped to original dealer
10/31/2006	95	Meade Lexus of Southfield Southfield, MI 248-372-7100 meadelexus.com	Vehicle sold
11/03/2006		Michigan Motor Vehicle Dept. Waterford, MI Title #167T3070247	Title or registration issued First owner reported Titled or registered as personal vehicle
01/16/2009		Lexus, a Division of Toyota Motor Sales, USA, Inc.	<p>Manufacturer Safety recall issued NHTSA #09V020 Recall #9LA SAFETY RECALL 9LA - CERTAIN 2006 - 2007 GS, 2006 - 2008 IS AND 2007 - 2008 LS VEHICLES, REPLACEMENT OF FUEL DELIVERY PIPES (FUEL RAILS) Status: Remedy Available</p> <p>Locate an authorized Lexus dealer near you to schedule an appointment</p> <p>- Learn more about this recall</p>
<p>Description: Toyota is recalling 214,570 Model Year 2006-2008 Lexus IS, Model Year 2006-2007 GS and Model Year 2007-2008 IS passenger vehicles equipped with aluminum fuel delivery pipes (fuel rails). Ethanol fuels with a low moisture content will corrode the internal surface of the fuel rails. As this condition progresses, the engine malfunction indicator light may illuminate.</p> <p>Over time, the corrosion may create a pinhole resulting in fuel leakage. Fuel leakage, in the presence of an ignition source, could result in a fire.</p> <p>Remedy: Dealers will inspect and replace the fuel delivery pipes free of charge. Owners may contact Toyota/Lexus at 1-800-255-3987.</p>			
01/17/2009		Lexus, a Division of Toyota Motor Sales, USA, Inc.	<p>Manufacturer Service Campaign issued Campaign #9LB SPECIAL SERVICE CAMPAIGN 9LB - CERTAIN 2006 - 2008 GS AND IS VEHICLES, REAR BRAKE CALIPER INSPECTION Campaign #9LC SPECIAL SERVICE CAMPAIGN 9LC - CERTAIN 2006 - 2007 GS, IS AND RX400H VEHICLES, ELECTRIC POWER STEERING LINK (EPS) ASSEMBLY REPLACEMENT Status: Remedy Available</p> <p>Locate an authorized Lexus dealer near you to schedule an appointment</p> <p>- Learn more about this campaign</p>

Description: This is an important Special Service Campaign.

Remedy: Please contact your authorized Lexus dealer to make an appointment to inspect and lubricate the rear caliper slide pins as soon as possible.

01/26/2011

Lexus, a Division of
Toyota Motor Sales,
USA, Inc.

Manufacturer Safety recall issued
NHTSA #11V029
Recall #BLA SAFETY RECALL BLA CERTAIN
2006 - 2007
GS, 2006 - EARLY 2009 IS 250 AND 2006 -
EARLY 2008
IS 350 VEHICLES INSUFFICIENT
TIGHTENING OF THE
FUEL PRESSURE SENSOR
Status: Remedy Available

Locate an authorized [Lexus dealer](#) near you to
schedule an appointment

- [Learn more about this recall](#)

Description: Toyota is recalling certain model year 2006-2009 Lexus IS and model year 2006-2007 Lexus GS vehicles. Due to insufficient tightening of the fuel pressure sensor connected to an engine fuel delivery pipe with nickel phosphorus plating, there is a possibility that, over time, the pressure sensor could loosen. If loosening occurs, fuel could leak past a gasket used in the connection between the sensor and the pipe and through the threaded portion of the sensor.

Fuel leakage, in the presence of an ignition source, could result in a fire.

Remedy: Dealers will inspect for fuel leakage from the threaded portion of the fuel pressure sensor and if a fuel leak is not confirmed, dealers will further tighten the fuel pressure sensor with the proper torque. If a fuel leak is confirmed, the gasket between the sensor and the fuel deliver pipe will be replaced with a new one, and the sensor will be tightened with the proper torque. This service will be performed free of charge. The safety recall began on march 7, 2011. Owners may contact Toyota at 1-800-331-4331.

02/24/2011

Lexus, a Division of
Toyota Motor Sales,
USA, Inc.

Manufacturer Safety recall issued
NHTSA #11V115
Recall #BLB SAFETY RECALL BLB - 2006 -
EARLY 2007
MODEL YEAR GS 300 AND GS 350 AWD
VEHICLES PLASTIC
PAD EMBEDDED INTO THE FLOOR CARPET
Status: Remedy Available

Locate an authorized [Lexus dealer](#) near you to
schedule an appointment

- [Learn more about this recall](#)

Description: Toyota is recalling certain Model Year 2006 and 2007 Lexus GS300 and GS350 all wheel drive (AWD) vehicles. There is a possibility that the plastic pad embedded into the floor carpet may interfere with the operation of the accelerator pedal.

The accelerator pedal could temporarily become stuck in a partially depressed position rather than return to the idle position. A stuck accelerator pedal may result in unintended and sustained vehicle speeds and make it difficult to stop increasing the risk of a crash.

Remedy: Dealers will modify the plastic pad on the floor carpet free of charge. The manufacturer has not yet provided an owner notification schedule. Owners may contact Toyota at 1-800-331-4331.

10/15/2014

Lexus, a Division of
Toyota Motor Sales,
USA, Inc.

Manufacturer Safety recall issued
NHTSA #14V647
Recall #ELF SAFETY RECALL ELF - REMEDY
NOTICE -
VARIOUS MODELS - POTENTIAL FUEL
PRESSURE SENSOR

LEAK
Status: Remedy Available

Locate an authorized [Lexus dealer](#) near you to schedule an appointment

- [Learn more about this recall](#)

Description: In the subject vehicles, the sealing property of the gasket seated in between the pressure sensor and the fuel delivery pipe could become degraded. During vehicle operation, fuel could leak past the gasket.

In the presence of an ignition source, this could increase the risk of a vehicle fire.

Remedy: Any authorized Lexus dealership will repair the fuel pressure sensor sealing surface and replace the gasket at No Charge to you.

Have Questions? Consumers, please visit our Help Center at www.carfax.eu



Glossary

[View Full Glossary](#)

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Lexus Recall / Service Campaign

Toyota Motor Sales, USA, Inc. provides CARFAX with recall and service campaign information for vehicles originally marketed or sold in the United States of America, its territories, and Mexico. Only open safety or emissions recalls and service campaigns where the remedy has not been completed, will be listed. While Toyota provides data updates to CARFAX on a regular basis, this report may not include very recent activity. For the most current information on recall and campaign activity for any Lexus vehicle, you must go to <http://toyota.com/recall>.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2018 CARFAX Europe GmbH, a unit of IHS Markit. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.

6/28/18 5:41:54 PM (CDT)